

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2024

Submitted Date:

05/30/2024

Document Number:

699108646

FIELD INSPECTION FORMLoc ID 453038 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481797	TANK BATTERY	AC	03/22/2022		-	Jagged 4N64W08 1-12 Tank Battery	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Load out control tank is missing the capacity label and will need that installed. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/12/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location Sign		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: VRU	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird netting around the methanol tank needs to be fixed or replaced. See attached photos		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	07/12/2024
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 13		
Comment:	3 Sheds		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment: The 1N & 2N separators are currently torn apart for maintenance did not include the bird protectors for them.			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment: Compressed air storage			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment: ECO Vapor			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment: Air Compressor			
Corrective Action:			Date:
Type: Emission Control Device	# 11		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 12		
Comment: 1N & 2N are LO/TO for maintenance			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1		STEEL AST		40.326200,-104.575300	
Comment: No capacity label						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

OTHER	1	OTHER	STEEL AST			
Comment: Bulk Seperator						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 238 BBLs						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 210 BBLs						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	8	400 BBLs	FIBERGLASS AST		40.326100,-104.575300	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	OTHER	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) 538 BBLs		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481797

Type: TANK

API Number: -

Status: AC

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI Tank Battery

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>On Tuesday, May 28, 2024, at approximately 9:00 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</div> <div>Location: Jagged 4N64W08 1-12 Tank Battery</div> <div>Operator: Chevron/PDC</div> <div>Location ID: 481797</div> <div>County: Weld</div> <div>During the inspection, SI tank battery was observed. The following possible compliance issues were identified:</div> <div>Capacity Label: Load out control tank is missing the capacity label and will need that installed. Install sign to comply with Rule 605.h. Corrective Action deadline: 7/12/2024.</div> <div>Netting: Bird netting around the methanol tank needs to be fixed or replaced. Install or repair wildlife protection equipment. Corrective Action deadline: 7/12/2024.</div> <div>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Attached are photos, an annotation report, and an issues report.</div> <div>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</div>	burnsa	05/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699108647	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567677