

Indian Springs 2

API 05-067-06289

Response to Field Insp 714000510 from Corey Mcdonough/ECMC
dated 03/06/2024




ROBERT L BAYLESS
PRODUCER LLC

BEFORE

GOOD HOUSEKEEPING:

Weed debris around tanks



AFTER

Completed 03/22/2024



Indian Springs 2

API 05-067-06289

Response to Field Insp 714000510 from Corey McDonough/ECMC
dated 03/06/2024





ROBERT L BAYLESS
PRODUCER LLC

BEFORE

STORMWATER BMP:

Gully erosion forming



AFTER

BMP installed (rock) by Ridgeline 05/08/2024



Indian Springs 2

API 05-067-06289

Response to Field Insp 714000510 from Corey McDonough/ECMC
dated 03/06/2024



ROBERT L BAYLESS
PRODUCER LLC

BEFORE

STORMWATER BMP:

Gully erosion forming



AFTER

Erosion removed by Ridgeline 05/08/2024

