

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403809758

Date Received:

05/31/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Arauzo, Steven

steven.arauza@state.co.us

Laramie

cogccnotifications@laramie-energy.com

Toews, Wesley

wtoews@blm.gov

### ECMC INSPECTION SUMMARY:

FIR Document Number: 696205730

Inspection Date: 04/04/2024

FIR Submit Date: 04/10/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 312625

Location Name: Horseshoe Canyon Number: 3-28 Pad County: \_\_\_\_\_

Qtrqtr: NWN Sec: 28 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.248667 Longitude: -108.227953

### FACILITY - API Number: 05-077- -00 Facility ID: 312625

Facility Name: Horseshoe Canyon Number: 3-28 Pad

Qtrqtr: NWN Sec: 28 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.248667 Longitude: -108.227953

### CORRECTIVE ACTIONS:

1 CA# 194185

Corrective Action: Comply with ECMC 1004 Rules and conduct additional reclamation on the Location. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage site until Final Reclamation has passed.

Date: 05/31/2024

Response: CA COMPLETED

Date of Completion: 05/31/2024

Operator Comment: We are coordinating with BLM for reclamation repairs and seeding. Once approval is granted work will begin. It is estimated that work will be finalized in 7-10 days.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

2 CA# 194186

Corrective Action: Comply with Rule 1002.f. Install or repair required stormwater and erosion control BMPs in accordance with good engineering practice, and maintain in proper functioning condition to minimize erosion, degradation and sediment transport.

Additional reclamation is also being required in this report: Ensure erosion controls are implemented to stabilize the seeded soils.

Date: 04/17/2024

Response: CA COMPLETED

Date of Completion: 05/31/2024

Operator Comment: We are coordinating with BLM for reclamation repairs and seeding. Once approval is granted work will begin. It is estimated that work will be finalized in 7-10 days.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: \_\_\_\_\_

Title: Regulatory Specialsit

Date: 5/31/2024 11:57:06 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

Total Attach: 0 Files