

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2023

Submitted Date:

12/04/2023

Document Number:

711700002

FIELD INSPECTION FORM

Loc ID 312301 Inspector Name: DERANLEAU, GREG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Highberger, Kathryn		kathrynhighberger@gmail.com	
Quint, Craig		craig.quint@state.co.us	
Schure, Kym		kym.schure@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Bongers, Brent		bbongers@impetroresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221138	WELL	PR	04/01/2023	OW	075-09264	COLORADO 1-10	PR

General Comment:

Greg Deranleau conducted a **DESKTOP REVIEW** of this site to evaluate compliance with Corrective Action listed on FIR Doc #688000256 (1/31/2019). This Desktop FIR does not represent current field conditions of the wellsite or production facilities, but is related to Remediation Project 12431.

Prior inspection noted: "Based on field observations, hydrocarbon impacted soil related to the former oil skim pit appears to have been adequately removed (pending laboratory analytical confirmation) with the exception of the south wall" and assigned the following CA: "Remove additional soil from the south wall and provide confirmation soil sample results on a supplemental eForm 27."

Greg Deranleau reviewed the files for REM 12431 and found that additional excavation and sampling was conducted and documented on a Supplemental Form 27 and the Remediation Project was closed. Therefore, this Desktop FIR is being submitted to resolve the CA. This FIR does not address any other unresolved CAs and does not address current operational compliance on site.

Inspected Facilities

Facility ID: 221138 Type: WELL API Number: 075-09264 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: CA from FIR#688000256 (1/31/2019) has been addressed. Please see Form 27 doc #402218841 and attachments for full report.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
CA from 688000256 is resolved. Any other unresolved CAs or comments on other inspections are not addressed by this Desktop FIR.	deranleg	12/04/2023