

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2024

Submitted Date:

05/30/2024

Document Number:

699108646

FIELD INSPECTION FORMLoc ID 453038 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481797	TANK BATTERY	AC	03/22/2022		-	Jagged 4N64W08 1-12 Tank Battery	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Location Sign		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Load out control tank is missing the capacity label and will need that installed. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/12/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	The 1N & 2N separators are currently torn apart for maintenance did not include the bird protectors for them.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird netting around the methanol tank needs to be fixed or replaced. See attached photos		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	07/12/2024
Type: Gas Meter Run	# 13		

Comment: 3 Sheds		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 20		
Comment:		Date:	
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment: 1N & 2N are LO/TO for maintenance		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 11		
Comment:		Date:	
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment: Air Compressor		Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment: ECO Vapor		Date:	
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment: Compressed air storage		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,
Comment: Bulk Seperator					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	238 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		40.326200,-104.575300

Comment:		No capacity label					
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)		210 BBLs					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	8	400 BBLs	FIBERGLASS AST		40.326100,-104.575300		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)		538 BBLs				
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 481797 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI Tank Battery

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Tuesday, May 28, 2024, at approximately 9:00 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Location: Jagged 4N64W08 1-12 Tank Battery Operator: Chevron/PDC Location ID: 481797 County: Weld During the inspection, SI tank battery was observed. The following possible compliance issues were identified: Capacity Label: Load out control tank is missing the capacity label and will need that installed. Install sign to comply with Rule 605.h. Corrective Action deadline: 7/12/2024. Netting: Bird netting around the methanol tank needs to be fixed or replaced. Install or repair wildlife protection equipment. Corrective Action deadline: 7/12/2024. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Attached are photos, an annotation report, and an issues report. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	05/30/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403807769	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567684
699108647	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567677