

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas.

Section/Township/Range: 1 7S95W

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9692 Lack of stabilization/compaction



Photo # 9693 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9694 Lack of stabilization/compaction



Photo # 9695 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9696 Lack of stabilization/compaction



Photo # 9697 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9698 Lack of stabilization/compaction