

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403807855

Date Received:

05/30/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Thomas, John 505-326-2659

notices@rlbayless.com

Thomas, John 505-326-2659

jthomas@rlbayless.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000510

Inspection Date: 03/06/2024

FIR Submit Date: 03/07/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC

Company Number: 6720

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

### LOCATION - Location ID: 325387

Location Name: INDIAN SPRINGS-N33N10W Number: 3SWNE County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135697 Longitude: -107.917990

### FACILITY - API Number: 05-067-00 Facility ID: 325387

Facility Name: INDIAN SPRINGS-N33N10W Number: 3SWNE

Qtrqtr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135697 Longitude: -107.917990

### CORRECTIVE ACTIONS:

1 ☒ CA# 192753

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 03/14/2024

Response: CA COMPLETED

Date of Completion: 03/22/2024

Operator Comment: weeds removed, see attached

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

2  CA# 192754

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 03/09/2024

Response: CA COMPLETED

Date of Completion: 05/08/2024

Operator Comment:	BMPs installed, see attached
-------------------	------------------------------

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Helen Trujillo

Signed:

Title: Prod & Reg Analyst

Date: 5/30/2024 9:39:16 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403807855	FIR RESOLUTION SUBMITTED
403807860	Photos

Total Attach: 2 Files