

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403786671

Date Received:  
06/11/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
.TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301803  
Inspection Date: 03/07/2024 FIR Submit Date: 03/11/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 333109

Location Name: GM Number: 41-4 County:  
Qtrqtr: Lot 1 Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.471352 Longitude: -108.107307

FACILITY - API Number: 05-045-00 Facility ID: 333109

Facility Name: GM Number: 41-4  
Qtrqtr: Lot 1 Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.471352 Longitude: -108.107307

CORRECTIVE ACTIONS:

1 CA# 192923

Corrective Action: Secure load line to comply with Rule 608.e. Date: 03/16/2024

Response: CA COMPLETED Date of Completion: 03/26/2024

Operator Comment: Loadline has been plugged. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**2** CA# 192924

Corrective Action: Remove stored equipment to comply with Rule 606.

Date: 03/18/2024

Response: CA COMPLETED

Date of Completion: 03/26/2024

Operator Comment: Equipment has been removed. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**3** CA# 192925

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/26/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #192923: Loadline has been plugged. Corrective Action complete.  
CA #192924: Equipment has been removed. Corrective Action complete.  
CA #192925: Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 6/11/2024 10:37:11 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

Document Number	Description

Total Attach: 0 Files