

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403787085

Date Received:  
06/12/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301795  
Inspection Date: 03/05/2024 FIR Submit Date: 03/07/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335111

Location Name: WILLIAMS-66S96W Number: 34NWSW County: \_\_\_\_\_  
Qtrqtr: NWS Sec: 34 Twp: 6S Range: 96W Meridian: 6  
W  
Latitude: 39.479743 Longitude: -108.100019

FACILITY - API Number: 05-045-00 Facility ID: 335111

Facility Name: WILLIAMS-66S96W Number: 34NWSW  
Qtrqtr: NWS Sec: 34 Twp: 6S Range: 96W Meridian: 6  
W  
Latitude: 39.479743 Longitude: -108.100019

CORRECTIVE ACTIONS:

1  CA# 192813

Corrective Action: Install sign to comply with Rule 605.d. Date: 04/06/2024

Response: CA COMPLETED Date of Completion: 04/10/2024

Operator Comment: New wellhead signs have been installed. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2  CA# 192814

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 05/20/2024

Operator  
Comment:

Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #192813: New wellhead signs have been installed. Corrective Action complete.  
CA #192813: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/12/2024 7:44:00 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403787085	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files