

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403788739

Date Received:

06/12/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708301678

Inspection Date: 02/13/2024

FIR Submit Date: 02/16/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 433948

Location Name: Puckett Number: GM 11-28 County: \_\_\_\_\_

Qtrqtr: Lot 4 Sec: 28 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.498867 Longitude: -108.119486

### FACILITY - API Number: 05-045- -00 Facility ID: 433948

Facility Name: Puckett Number: GM 11-28

Qtrqtr: Lot 4 Sec: 28 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.498867 Longitude: -108.119486

### CORRECTIVE ACTIONS:

1 ☒ CA# 192160

Corrective Action: Secure load line to comply with Rule 608.e.

Date: 03/02/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Produced water tank loadline has been plugged. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2 ☒ CA# 192161

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/02/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator  
Comment:

Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #192160: Produced water tank loadline has been plugged. Corrective Action complete.  
CA #192161: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/12/2024 8:24:39 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403788739	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files