

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403780121

Date Received:

05/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Smith, Chris

Phone

970-330-7034

Email

smithenergy@live.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698602005

Inspection Date: 04/23/2024

FIR Submit Date: 05/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SMITH ENERGY LLC

Company Number: 10536

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

LOCATION - Location ID: 303574

Location Name: CROSSLAND-64N46W Number: 2NWNE County: YUMA

Qtrqtr: NWNE Sec: 2 Twp: 4N Range: 46W Meridian: 6

Latitude: 40.350219 Longitude: -102.478589

FACILITY - API Number: 05-125- -00 Facility ID: 253311

Facility Name: CROSSLAND Number: 1-2

Qtrqtr: NWNE Sec: 2 Twp: 4N Range: 46W Meridian: 6

Latitude: 40.350219 Longitude: -102.478589

CORRECTIVE ACTIONS:

1 CA# 194888

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1). (2).

Date: 03/11/2024

Corrective action date remains the same to document period of non-compliance.

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

There was a valve in the ground already that was hard to see so we added pvc to make it easier to see back on March 1. Pictures are attached, and this has been submitted under document id inspection: 403780088. Thanks

Operator Comment:	
ECMC Decision:	
ECMC Representative:	

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	There was a valve in the ground already that was hard to see so we added pvc to make it easier to see back on March 1. Pictures are attached, and this has been submitted under document id inspection: 403780088. Thanks
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Chris Smith	Signed:
Title: Manager	Date: 5/6/2024 10:50:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403780121	FIR RESOLUTION SUBMITTED
403780123	Pictures showing valve that was in ground.

Total Attach: 2 Files