

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403794116

Date Received:

06/18/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Toews, Wesley

wtoews@blm.gov

Trujillo, Aaron

aaron.trujillo@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708902014

Inspection Date: 10/20/2023

FIR Submit Date: 10/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335176

Location Name: FEDERAL-66S94W Number: 19NESE County: _____

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

FACILITY - API Number: 05-045- -00 Facility ID: 335176

Facility Name: FEDERAL-66S94W Number: 19NESE

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

CORRECTIVE ACTIONS:

1 ☒ CA# 185752

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 12/04/2023

The ditch has been maintained. Location and access road have been bladed/graded to increase stabilization to

Operator Comment: prevent off-location transportation of sediment. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The ditch has been maintained. Location and access road have been bladed/graded to increase stabilization to prevent off-location transportation of sediment. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 6/18/2024 5:15:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403794116	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files