

Operator: BCEI
Location Name: Antelope G-29
Loc ID: 422161
Inspection: 696306429



Exhibit A



Exhibit B



Exhibit C

CA: Tumbleweed Debris at Separators and Wellheads; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that identified tumbleweeds and debris has been appropriately cleared from the location to comply with Rule 606.



Exhibit A



Exhibit B



Exhibit C

CA: Unmarked Risers at various Wellheads and Separators. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

CA Resolution: Operator has reported that various risers have now been appropriately marked to comply with Rule 1105.b.

CA: Heat Exhaust Stacks have been removed. Separators open to Atmosphere need to be closed. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Operator has reported that wildlife protection has been appropriately installed on the separators to comply with Rule 902.b.