

Operator: BCEI

Location Name: Antelope 11-20

Loc ID: 424418

Inspection: 696306459



Exhibit A

CA: Unmarked Risers at Wellheads and Separators. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

CA Resolution: Operator has reported that all identified risers have now been appropriately marked to comply with Rule 1105.b.



Exhibit A

CA: Panels - Panels in disrepair on South Wells. Comply with Rule 606

CA Resolution: Operator has reported that the identified fallen panels have been appropriately fixed/re-installed to comply with Rule 606.