

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2024

Submitted Date:

06/26/2024

Document Number:

714201248**FIELD INSPECTION FORM**Loc ID 327850 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247438	WELL	PR	11/01/2023	GW	123-15235	SHABLE 17-15G	SI

**General Comment:**[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER			,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			

Comment: [Some erosion south of tank battery. See attached photos.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 09/26/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">ECMC Inspection Report Summary</a> <a href="#">WEATHER CONDITIONS: sunny, dry ground.</a> <a href="#">On Tuesday, June 25, 2024 at approximately 1145, I, Inspector Brittani Santistevan, conducted an on-site inspection at SHABLE 17-15G (Noble Energy, Inc), at location ID: 327850 in WELD COUNTY, Colorado.</a> <a href="#">While there, I observed a shut in facility.</a> <a href="#">During this inspection the following possible compliance issues were observed:</a> <a href="#">1. It appears to be some erosion to location (South of tank battery) Install or repair required BMPs per Rule 1002.f.(2)C (Corrective Action Date: September 26, 2024) See attached photo #4-6.</a>  <a href="#">A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</a> <a href="#">This is a summary of inspection report.</a>	santistb	06/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201249	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6602749">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6602749</a>