

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403824205

Date Received:

06/13/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Shorty, Priscilla

Phone

505-324-5188

Email

pshorty@hilcorp.com

FarmingtonRegulatoryTechs@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000774

Inspection Date: 05/21/2024

FIR Submit Date: 05/29/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON

State: TX

Zip: 77208

LOCATION - Location ID: 385841

Location Name: HUBER-THORN-N35N8W Number: 34SWNE County: _____

Qtrqtr: SWNE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.261576 Longitude: -107.730795

FACILITY - API Number: 05-067-

-00

Facility ID: 385841

Facility Name: HUBER-THORN-N35N8W Number: 34SWNE

Qtrqtr: SWNE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.261576 Longitude: -107.730795

CORRECTIVE ACTIONS:

1 ☒ CA# 195460

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 06/12/2024

Corrective action completed. See attached photos.

Operator
Comment:

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 6/13/2024 2:21:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403824205	FIR RESOLUTION SUBMITTED
403824210	Huber-Thorn 1-34_Resolved Photos

Total Attach: 2 Files