

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601192

FIELD INSPECTION FORM

Loc ID 314215 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BEAR STACY L		stacy@strachanexploration.com	
Harms, Jason		Jason@strachanexploration.com	
Jordan LaPlante		jordan_laplante@fws.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275439	WELL	PR	06/01/2017	GW	099-06881	GRUENLOH 2	RI

General Comment:

This is a follow up of the previous inspection #713600839 at the GRUENLOH #2 wellsite. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

	Type	TANK LABELS/PLACARDS
	Comment:	There was no tank labels observed at the open top tank. Previous corrective action was not completed.
	Corrective Action:	Install sign to comply with Rule 605.h. Date:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		
Comment:		Netting has now been installed over the open top tank. Operator must ensure that all open top tanks of all other wells have netting to prevent wildlife mortality.			
Corrective Action:					Date: <input style="width: 80%;" type="text"/>

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
		Date: <input style="width: 80%;" type="text"/>		

Venting:

Yes/No		
Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:		
		Date: <input style="width: 80%;" type="text"/>

Flaring:

Type		
Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:		
		Date: <input style="width: 80%;" type="text"/>

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Tanks		37.972960	-102.501200
Comment	The previous inspection observed no wildlife protections or netting on the open top tank. There were 4 dead migratory birds found floating in the tank covered with oily E&P waste. Operator did not comply with the previous corrective action to inform ECMC staff to observe the fluid removal from the tank. Wildlife mortality instances will be referred to enforcement.			
Corrective Action				Date:

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601193	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604876