

Operator: BCEI
Location Name: Antelope I-29
Loc ID: 422173
Inspection: 696306431



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G

CA: All Wellhead Signs have faded no longer visible; see photos. Install sign to comply with Rule 605.d.

CA Resolution: Operator has reported that Wellhead signage has been updated and installed appropriately to comply with Rule 605.d.

CA: Unmarked Risers at various Wellheads and Separators. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

CA Resolution: Operator reported that identified risers have been marked appropriately, and shared additional photo regarding a marked riser to comply with Rule 1105.b.