

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1877 From entrance to location



Photo # 1878 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1879 Location



Photo # 1880 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1881 Location



Photo # 1882 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1883 Location



Photo # 1884 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1885 Location



Photo # 1886 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1887 Location



Photo # 1888 Chemical tank label weathered/faded & some required info is illegible

Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 1889 PRV vent line does not comply with CECMC pressure safety device rules