

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2024

Submitted Date:

07/01/2024

Document Number:

714201264**FIELD INSPECTION FORM**Loc ID 332862 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240882	WELL	PR	06/01/2023	GW	123-08670	MUSICK-MCCLINTOCK 1	SI

**General Comment:**[THIS IS A FOLLOW UP INSPECTION.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate (very faded, consider replacing)		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	One tank does not display contents, capacity. Other tank does not display signage (contents, capacity, NFPA placard) See attached photo.		
Corrective Action:	Install sign to Comply with Rule 605.h.	Date:	04/19/2024

Emergency Contact Number:

Comment:

Corrective Action:  Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:	debris/weeds on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	04/19/2024
Type	OTHER		
Comment:	It appears tank was leaking. See attached photo.		
Corrective Action:	Comply with Rule 609.	Date:	04/19/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	it appears all equipment count remains the same as documented in previous inspection DOC#: 714200815.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Inspector Name: Santistevan, Brittani

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>This is a follow up inspection to previous inspection DOC#: 714200815 . All previous corrective actions assigned to this location stated in previous inspection DOC#: 714200815 have NOT been resolved. All previous corrective actions have been re-assigned to this location with their original corrective action dates. No new corrective actions were observed at the time of re-inspection. Please review my findings below.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: cloudy, dry ground. On Thursday, June 27, 2024 at approximately 1145, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-McCLINTOCK #1 (KP Kauffman Company Inc), at location ID: 332862 in WELD COUNTY, Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. Weeds/debris on various areas of location. Comply with Rule 606. (Corrective Action Date: April 19, 2024) See attached photo #2, 3, 6-10. 2. It appears tank was leaking inside containment. Comply with Rule 609. (Corrective Action Date: April 19, 2024) See attached photo #4. 3. It appears one tank does not contain capacity and another tank does not display any signage (No NFPA placard, capacity, contents) Install sign to comply with Rule 605.h. (Corrective Action Date: April 19, 2024) See attached photo #5, 9.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	06/27/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201265	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608159">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608159</a>