

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2024

Submitted Date:

07/01/2024

Document Number:

714201266

**FIELD INSPECTION FORM**

Loc ID 311363 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247274	WELL	PR	06/01/2023	GW	123-15071	MUSICK MCCLINTOCK 7	SI

**General Comment:**

[THIS IS A WELLHEAD INSPECTION.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Operator name no longer legible. See attached photo		
Corrective Action:	Comply with Rule 605.		Date: 08/01/2024
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment at south end of pumpjack. See attached photo.		
Corrective Action:	Comply with Rule 606.		Date: 08/01/2024
Type	WEEDS		
Comment:	overgrown vegetation surrounding pumpjack. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 08/01/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Pump Jack			# 1
Comment:			
Corrective Action:			Date:
Type: Bradenhead			# 1
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 247274 Type: WELL API Number: 123-15071 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/26/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 25 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      WEATHER CONDITIONS: cloudy, dry ground.                      On Thursday, June 27, 2024 at approximately 1215, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-McCLINTOCK #7 (KP Kauffman Company Inc), at                      API #: 50-123-15071 in WELD COUNTY, Colorado.                      While there, I observed a shut in facility.                      During this inspection the following possible compliance issues were observed:                      1. Overgrown vegetation surrounding pumpjack. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #3-5.                      2. It appears operators name is no longer legible on pumpjack sign. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #1.                      3. Unused equipment south end of pumpjack. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	07/01/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201267	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608160">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608160</a>