

**Operator: BCEI**  
**Location Name: Antelope F-15 PAD**  
**Loc ID: 429977**  
**Inspection: 696306463**



Exhibit A



**Exhibit B**

**CA:** Unmarked Risers at Antelope 31-34-15HNB Separator Site; see photos. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

**CA Resolution:** Operator has reported that identified risers have been appropriately marked to comply with Rule 1105.b.



Exhibit A



Exhibit B



Exhibit C



**Exhibit D**

**CA:** Tank Labels STILL remain unaddressed - EAST TANK BATTERY LABELS - #1336 - NFPA and Content. #220404 - Content, Capacity and NFPA. #220403 - NFPA. #220402 - Capacity and Content. #220401 -NFPA. East side of East Tanks - far North Tank -Capacity. Far South Tank - Content, Capacity and NFPA. See photos. Same Corrective Action Date remains the same. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has reported that appropriate labels have now been installed to comply with Rule 605.h.