

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403834244

Date Received:

06/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ross, Rikki

970-896-5665

rikki.ross@fulcrumeo.com

Penner, annalee

annalee@fulcrumef.com

Fulcrum

inspections@fulcrumeo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 707800928

Inspection Date: 05/01/2024

FIR Submit Date: 05/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC

Company Number: 10805

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 467526

Location Name: Spicer S32 Number: Annex Pad County: _____

Qtrqtr: SWS Sec: 32 Twp: 7N Range: 80W Meridian: 6

W

Latitude: 40.529551 Longitude: -106.403819

FACILITY - API Number: 05-057- -00 Facility ID: 467526

Facility Name: Spicer S32 Number: Annex Pad

Qtrqtr: SWS Sec: 32 Twp: 7N Range: 80W Meridian: 6

W

Latitude: 40.529551 Longitude: -106.403819

CORRECTIVE ACTIONS:

1 ☒ CA# 195021

Corrective Action: Provide proper secondary containment

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Chemical totes have been removed from location.

Operator
Comment:

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 ☒ CA# 195022

Corrective Action: Provide proper labeling and put into service or remove

Date: 06/19/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator
Comment: Chemical tanks have been removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

3 ☒ CA# 195023

Corrective Action: Remove debris

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 06/05/2024

Operator
Comment: Debris has been removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

4 ☒ CA# 195024

Corrective Action: Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.

Date: 06/19/2024

Response: CA COMPLETED

Date of Completion: 06/05/2024

Operator
Comment: Stains and stained material have been cleaned up and removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

5 ☒ CA# 195025

Corrective Action: Evacuate fluids in containments to provide adequate space in case of a spill

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 06/05/2024

Operator
Comment: Containment has been sucked out.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed:

Title: EHS Field Advisor

Date: 6/24/2024 3:48:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403834244	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files