

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403842421

Date Received:
07/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ross, Rikki</u>	<u>970-896-5665</u>	<u>rikki.ross@fulcrumeo.com</u>
<u>. Fulcrum</u>		<u>inspections@fulcrumeo.com</u>
<u>Penner, annalee</u>		<u>annalee@fulcrumef.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 707800941
Inspection Date: 05/01/2024 FIR Submit Date: 05/10/2024 FIR Status: _____

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC Company Number: 10805
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: _____
Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057-00 Facility ID: 447512

Facility Name: Open Range Number: 18
Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 CA# 195098

Corrective Action: Remove debris Date: 05/27/2024

Response: CA COMPLETED Date of Completion: 05/17/2024

Operator Comment: Debris has been removed from the location.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

[Empty text box for ECMC Representative]

2 CA# 195099

Corrective Action: Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.

Date: 05/27/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Operator Comment: Stains removed from location.

[Empty text box for Operator Comment]

ECMC Decision: Approved pending re-inspection

ECMC Representative:

[Empty text box for ECMC Representative]

3 CA# 195100

Corrective Action: Provide proper signage

Date: 06/27/2024

Response: CA COMPLETED

Date of Completion: 06/26/2024

Operator Comment: No sign is required and the tank is labeled as "Field Gas Liquid Knockout". API numbers have been added to all wellhead signs.

[Empty text box for Operator Comment]

ECMC Decision: Approved pending re-inspection

ECMC Representative:

[Empty text box for ECMC Representative]

4 CA# 195101

Corrective Action: Install, maintain or repair required BMPs

Date: 06/28/2024

Response: CA COMPLETED

Date of Completion: 06/19/2024

Operator Comment: The location has been bladed and rock was brought in to stabilize the pad.

[Empty text box for Operator Comment]

ECMC Decision: Approved pending re-inspection

ECMC Representative:

[Empty text box for ECMC Representative]

OPERATOR COMMENT AND SUBMITTAL

Comment:

[Empty text box for Operator Comment and Submittal]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: EHS Field Advisor

Date: 7/1/2024 6:55:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403842421	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files