

Gruenloh #2 Location Inspection repair photos 11APR24



Tank was emptied. We alerted Mr. Costa, who was not available, and gave us verbal directions to go ahead w the operation.







New netting installed. Berms were repaired. Volume of the tank stenciled on the tank.