

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601179**FIELD INSPECTION FORM**Loc ID 321213 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY L		stacy@strachanexploration.com	
Enforcement		dnr_ecmcenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206286	WELL	PR	11/01/2017	GW	011-06032	BOURNE 1	RI

General Comment:

This is a follow up of the previous reclamation inspections #713600504, #713600771 #713600827.
The previous inspection corrective actions have not been completed.
Non-compliance with the Rules will be referred to enforcement.
See attached photos and additional details within this report.

Note: Documentation (FIRR) showing completion of corrective actions is requested within 2 weeks.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	The sign at the tank battery has the incorrect Operator and is faded. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	There is an unused pipe riser at the wellhead with no OOSLAT. Abandoned risers need to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with 606.		Date:
Type	WEEDS		
Comment:	There are tall undesirable weeds at the location that need to be controlled and removed. It appears bare ground treatment was performed however the tall dry weed debris is a fire hazard and needs to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606.		Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	
Produced Water	Separator		
Comment:	There is still a dripping leak at the separator that has not been controlled. Previous corrective action was not completed and must be addressed immediately.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: COSTA, RYAN

Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	06/27/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403838233	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603813
713601180	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603811