

**Gordon Engineering Inc
Federal 9-2
Location ID: 315302**



Operator is responsible for replacing illegible signs



Relief riser protective cap missing

**Gordon Engineering Inc
Federal 9-2
Location ID: 315302**



Location from Southeast corner



Location from Southwest corner

**Gordon Engineering Inc
Federal 9-2
Location ID: 315302**



Location from Northwest corner

Location from Northeast corner