

Gordon Engineering Inc
Federal 10-4
Location ID: 315170



No access to Bradenhead



Relief riser missing cap

Gordon Engineering Inc
Federal 10-4
Location ID: 315170



Oil staining



Location from Southwest entrance

**Gordon Engineering Inc
Federal 10-4
Location ID: 315170**



Location from Southeast corner



Location from Northeast corner