

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2024

Submitted Date:

07/08/2024

Document Number:

715500367**FIELD INSPECTION FORM**Loc ID 315302 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 34720Name of Operator: GORDON ENGINEERING INCAddress: PO BOX 113City: SPRINGDALE State: UT Zip: 84767**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
-
- 3 Number of Corrective Actions
-
- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Bryan, Nicholas	(385) 250-4548	nickbryan85@gmail.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103784	PIT	AC	09/16/2022		-	FEDERAL 9-2	AC
230595	WELL	PR	10/01/2021	GW	103-08263	FEDERAL 9-2	PR

General Comment:**ECMC Inspection Report Summary**

On Monday, 07/08/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Gordon Engineering Inc. on the Federal 9-2 well, Location #315302, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to issues observed during Insp. #702501660 on 7/19/23. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Relief riser missing cap.
2. No annual Bradenhead test.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (970) 618-0811 or 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Livestock wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Tank Livestock wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Relief riser missing protective cap		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: 07/24/2024
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No annual Bradenhead test reports in database		

Corrective Action:	For all Wells other than coalbed methane Wells, an Operator will perform an annual Bradenhead test and submit the data to the Director on a Form 17 or other Director-approved method.		Date:	08/08/2024
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Wellhead tree			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		,
Comment:	Buried ground level.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	30
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	103784	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	230595	Type:	WELL	API Number:	103-08263	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	April 2024 Production Report								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 103784Lat: 39.888200Long: -108.730600

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective _____

Date: _____

Fencing:Fencing Type: Livestock

Fencing Condition: _____

Comment: _____

Corrective _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

Corrective _____

Date: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500368	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6615307