

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

713601226

FIELD INSPECTION FORM

Loc ID 334553 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Newville, Toni		toni_newville@oxy.com	
Oxy		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211835	WELL	PA	12/08/2022	CO2	055-06072	SHEEP MOUNTAIN UNIT 4-4-P	RI
334553	LOCATION	AC			-	Sheep Mountain Unit 6-4-I	RI

General Comment:

This is a follow up of the previous inspection (#713600946) at the Sheep Mountain Unit 6-4-I location. See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	There has been recent noxious weed control performed at the location.		
Corrective Action:		Date:	
Type	TRASH		
Comment:	The trash was picked up since previous inspection.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	The pile of brush debris still remains at the northeast side of the location which will need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	07/19/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	The orange safety fence is still in disrepair and should be removed if no longer needed. The wellhead has been partly backfilled and is no longer a danger for wildlife or livestock.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Piles		37.721090	-105.222370
Comment	The pile of E&P waste stored at the northeast side of the location needs to be removed. This pile has been stored for nearly a year and must be removed and properly disposed.			
Corrective Action	Comply with Rule 905.			Date: 07/19/2024

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601227	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6618466