

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403840165

Date Received:

06/28/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 600 17TH STREET STE 1400S

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

inspections@catamountep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000865

Inspection Date: 06/18/2024

FIR Submit Date: 06/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 600 17TH STREET STE 1400S

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 438700

Location Name: Carpenter Number: 32-6-3 County: _____

Qtrqtr: NWSE Sec: 3 Twp: 32N Range: 6W Meridian: N

Latitude: 37.045730 Longitude: -107.484670

FACILITY - API Number: 05-067- -00 Facility ID: 438700

Facility Name: Carpenter Number: 32-6-3

Qtrqtr: NWSE Sec: 3 Twp: 32N Range: 6W Meridian: N

Latitude: 37.045730 Longitude: -107.484670

CORRECTIVE ACTIONS:

1 ☒ CA# 196097

Corrective Action: Spot seeding needs to be conducted within portions of the interim reclamation areas with poor revegetation. Comply with rule 1003.f treat/remove weeds. 7/31/2024 CA given for fall seeding window.

Date: 07/31/2024

Response: CA COMPLETED

Date of Completion: 06/27/2024

Operator Comment: Harrowed and seeded bare slopes, removed weeds.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

2 CA# 196098

Corrective Action:	Storm water BMPs and erosion controls (ie: mulch, hydromulch, straw blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.	Date: <u>07/01/2024</u>
--------------------	---	-------------------------

Response: CA COMPLETED Date of Completion: 06/28/2024

Operator Comment:	Installed wattles and seeded/mulched areas with exposed/bare soils.
-------------------	---

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL	

Comment:	
----------	--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond Signed: _____

Title: Geo/Eng Tech Date: 6/28/2024 1:48:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403840165	FIR RESOLUTION SUBMITTED
403840366	Remedial Report

Total Attach: 2 Files