

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

710500324**FIELD INSPECTION FORM**Loc ID 485654 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10763Name of Operator: BNL (ENTERPRISE) INCAddress: 2011 FOREST AVENUECity: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kondrat, Peter	970-759-5370	pkondrat@bluestarhelium.com	<a href="#">All Inspections</a>
Costa, Ryan		ryan.costa@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485740	WELL	DG	01/31/2024		071-09933	Bolling 04 SESW 2960	EI

**General Comment:**

This is an Environmental Inspection for the Bolling # 4 well location located in Las Animas County, Co There is an open Remediation Project # 34840.

Location

Overall Good: ☐

Emergency Contact Number:

Comment: Sign at entrance to location

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	485740	Type:	WELL	API Number:	071-09933	Status:	DG	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: BMPs Inadequate, sections of Silt Fence need to be repaired

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/15/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Drill Cuttings identified in Remediation Project # 34840 have been removed from the location.	sanchezcc	07/11/2024
Sections of silt fence need to be repaired in accordance with Rule 1002.f.(2)C	sanchezcc	07/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500326	Inspection # 710500324 Location Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619045">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619045</a>