

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403818719

Date Received:

07/15/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708903988

Inspection Date: 06/06/2024

FIR Submit Date: 06/06/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 334988

Location Name: FOSSIL CREEK-67S94W Number: 6SENE County: \_\_\_\_\_

Qtrqtr: SENE Sec: 6 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.470343 Longitude: -107.923225

### FACILITY - API Number: 05-045- -00 Facility ID: 334988

Facility Name: FOSSIL CREEK-67S94W Number: 6SENE

Qtrqtr: SENE Sec: 6 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.470343 Longitude: -107.923225

### CORRECTIVE ACTIONS:

1 ☒ CA# 195716

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 06/07/2024

Response: CA COMPLETED

Date of Completion: 06/10/2024

Operator  
Comment:

The leaking grease fitting has been replaced and is no longer leaking. Corrective Action complete.

ECMC Decision: Approved pending re-inspection



Comply with CECMC pressure safety device rules

Date: 06/13/2024

CA COMPLETED

Date of Completion: 06/10/2024

Cap has been installed on the PRV vent line. Corrective Action complete.

Approved pending re-inspection

OPERATOR COMMENT AND SUBMITTAL

CA# 195716: The leaking grease fitting has been replaced and is no longer leaking. Corrective Action complete.  
CA# 195717: Cap has been installed on the PRV vent line. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Jordan Veith

Signed:

TEP Representative

Date: 7/15/2024 1:47:08 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403818719	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files