

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/09/2024

Document Number:

715500373

FIELD INSPECTION FORMLoc ID 316271 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260089	WELL	SI	03/01/2024	GW	103-10132	WRD DOW 20-11	SI

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 07/09/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Dow 20-11 well, Location #316271, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702502496 on 7/9/24 including 2 previous inspections since 6/14/23. The following Corrective Actions have not been resolved and original due dates remain:

1. Leaking equipment and stained soils.
2. Gas meter calibration out of compliance.

Refer to Inspection Photos for observed compliance issue.

While there during normal operations the following compliance issue was observed:

1. Weeds.

Refer to Inspection Photos for observed compliance issue.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560 or 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	07/17/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil under loadout pot.			
Corrective Action:	Remove and properly dispose of oily waste and impacted soils.			Date: 06/30/2023

Crude Oil	Tank	<= 1 bbl		
Comment:	Access cover leaking on crude oil tank.			
Corrective Action:	Repair equipment. Remove and properly dispose of oily waste and impacted soils.			Date: 06/10/2024

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.		
		Date:	01/28/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Unlined						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Unlined						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	260089	Type:	WELL	API Number:	103-10132	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Last Production - February 2024 April 2024 Production Report</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
				Material Handling And Spill Prevention		
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403849447	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616689
715500374	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616683