

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403832923

Date Received:

06/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306429
Inspection Date: 06/20/2024 FIR Submit Date: 06/18/2024 FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 422161

Location Name: Antelope Number: G-29 County: _____
Qtrqtr: SWN Sec: 29 Twp: 5N Range: 62W Meridian: 6
W
Latitude: 40.373340 Longitude: -104.352750

FACILITY - API Number: 05-123- -00 Facility ID: 422161

Facility Name: Antelope Number: G-29
Qtrqtr: SWN Sec: 29 Twp: 5N Range: 62W Meridian: 6
W
Latitude: 40.373340 Longitude: -104.352750

CORRECTIVE ACTIONS:

1 ☒ CA# 195982

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

Date: 07/19/2024

Response: CA COMPLETED Date of Completion: 06/21/2024

Operator Comment: Operator has reported that wildlife protection has been appropriately installed on the separators to comply with Rule 902.b.

ECMC Decision: Approved

ECMC
Representative: Approved

2 ☒ CA# 195983

Corrective Action: Comply with Rule 606

Date: 07/19/2024

Response: CA COMPLETED

Date of Completion: 06/21/2024

Operator
Comment: Operator has reported that identified tumbleweeds and debris has been appropriately cleared from the location to comply with Rule 606.

ECMC Decision: Approved

ECMC
Representative: Approved

3 ☒ CA# 195984

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until

Date: 07/19/2024

Response: CA COMPLETED

Date of Completion: 06/21/2024

Operator
Comment: Operator has reported that various risers have now been appropriately marked to comply with Rule 1105.b.

ECMC Decision: Approved

ECMC
Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr. Regulatory Analyst

Date: 6/24/2024 7:21:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403832923	FIR RESOLUTION SUBMITTED
403832928	Inspection Report Resolution

Total Attach: 2 Files