

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403832934

Date Received:

06/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306435

Inspection Date: 06/20/2024

FIR Submit Date: 06/20/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 441376

Location Name: Antelope Number: 14-21 Pad County: _____

Qtrqtr: SWS Sec: 21 Twp: 5N Range: 62W Meridian: 6
W

Latitude: 40.379335 Longitude: -104.335004

FACILITY - API Number: 05-123- -00 Facility ID: 441376

Facility Name: Antelope Number: 14-21 Pad

Qtrqtr: SWS Sec: 21 Twp: 5N Range: 62W Meridian: 6
W

Latitude: 40.379335 Longitude: -104.335004

CORRECTIVE ACTIONS:

1 ☒ CA# 195988

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

Date: 07/19/2024

Response: CA COMPLETED

Date of Completion: 06/21/2024

Operator has reported that various risers have now been appropriately marked to comply with Rule 1105.b.

Approved

Approved

Comment: CA follow-up has been completed for this location.

Signed:

Date: 6/24/2024 7:32:36 AM

403832934	FIR RESOLUTION SUBMITTED
403832935	Inspection Resolution Report

Page 2 of 2