

WELL NAME: CROSSWORD 41-36 TR, API #: 071-08852, INSP. # 695109968



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION





PHOTO 3: ORIG WELLHEAD AND EQUIPMENT





PHOTO 4: TR WELLHEAD AND EQUIPMENT





PHOTO 5: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. REMOVE OR TREAT IMPACTED MATERIAL, REPAIR EQUIPMENT AND INSPECT AT REGULAR INTERVALS TO PREVENT IMPACTING ENVIRONMENT AROUND COMPRESSOR PER RULE 1002..(2).D. 10 DAYS TO HANDLE IMPACTED SOIL, THIS IS THE SECOND NOTICE TO REPAIR OR REPLACE EQUIPMENT IMMEDIATE ACTION IS REQUIRED.





PHOTO 6: OILY WASTE INSIDE COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 7-19-2024.





PHOTO 7: OILY WASTE INSIDE PRIME MOVER SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 7-19-2024.

