

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403809642

Date Received:  
06/04/2024

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 713900517  
Inspection Date: 04/04/2024 FIR Submit Date: 04/09/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 444717

Location Name: Anschutz Equus Farms Number: 4-62-20\_21 County: \_\_\_\_\_  
SWNW  
Qtrqr: SWN Sec: 20 Twp: 4N Range: 62W Meridian: 6  
W  
Latitude: 40.299603 Longitude: -104.356372

FACILITY - API Number: 05-123- -00 Facility ID: 444717

Facility Name: Anschutz Equus Farms Number: 4-62-20\_21  
SWNW  
Qtrqr: SWN Sec: 20 Twp: 4N Range: 62W Meridian: 6  
W  
Latitude: 40.299603 Longitude: -104.356372

**CORRECTIVE ACTIONS:**

**3** CA# 194150

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 05/13/2024

Response: CA COMPLETED Date of Completion: 05/29/2024

Operator Comment: Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Location currently complies with Rule 1002.c.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

4 CA# 194151

Corrective Action: Perform reclamation on areas not needed for production as well as current interim areas in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 05/13/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator Comment: Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth.. Location currently complies with Rule 1003.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst Date: 6/4/2024 5:41:45 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403809642	FIR RESOLUTION SUBMITTED
403812464	Inspection Report Resolution

Total Attach: 2 Files