

Storm Water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area. Location is approximately 240 yards from Beaver Creek & approximately 575 yards from the Colorado River.

Section/Township/Range: 23 6S94W

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 363 From inspection 708901771 conducted on 09/22/2023 Erosion & transport of sediment onto location/ insufficient BMP's



Photo # 2917 Erosion & transport of sediment onto location/ insufficient BMP's

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 355 From inspection 708901771 conducted on 09/22/2023 Erosion & transport of sediment onto location/ insufficient BMP's



Photo # 2918 Erosion & transport of sediment onto location/ insufficient BMP's

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 365 From inspection 708901771 conducted on 09/22/2023 Erosion & transport of sediment onto location/insufficient BMP's



Photo # 2919 Erosion & transport of sediment onto location/insufficient BMP's

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 386 From inspection 708901771 conducted on 09/22/2023 Erosion & transport of sediment onto location/ insufficient BMP's



Photo # 2920 Erosion & transport of sediment onto location/ insufficient BMP's

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 388 From inspection 708901771 conducted on 09/22/2023 Erosion & transport of sediment onto location/insufficient BMP's



Photo # 2921 Erosion & transport of sediment onto location/insufficient BMP's