

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2024

Submitted Date:

07/25/2024

Document Number:

694100405**FIELD INSPECTION FORM**Loc ID 470525 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All inspections
,		cogccinspection@pdce.com	All Inspections
Baker, Melissa	(970) 506-9272	melissa.baker@pdce.com	

General Comment:

This is an environmental inspection for Location ID 470525 Wiess TB. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☒

Spills:

Type	Area	Volume		
In Containment: No				
Comment: No spills/releases observed during inspection.				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 7/25/2024 Doc [#694100405]

Page 2 of 4

Location Construction

Location ID: 470525 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Comments: Erosion BMPs: Soil stock pile on site is not lined or contained with erosion control measures to prevent soil migration off site; nor does it appear to be labelled clean or contaminated.

Other BMPs: _____

Corrective Action: Operator to label the soil stock pile accordingly, remove the soil pile, and/or install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/01/202
4

Comment: Straw wattles are overloaded with sediment, need to be cleaned out or replaced and sediment pulled back. Sediment has migrated off site down into a ravine. All sediment needs to be pulled back onto the pad surface.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/01/2024

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill:

Estimated Spill Volume:

Comment: No spills/releases observed during inspection.

Corrective Action:

Date:

Reportable:

GPS: Lat Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100407	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639549

Date Run: 7/25/2024 Doc [#694100405]

Page 4 of 4