

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2024

Submitted Date:

07/24/2024

Document Number:

699506079

FIELD INSPECTION FORM

Loc ID 320662 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204342	WELL	PR	01/01/2023	GW	005-06427	CHURCH 7-A 41-2	PR

General Comment:

[There have been no changes to equipment on location since previous inspection.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: weeds unmanaged on location

Corrective Action: Comply with rule 606

Date: 08/08/2024

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 204342 Type: WELL API Number: 005-06427 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/02/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 7/24/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Church 7-A 41-2 Company Name- KPK API- 05-005-06427 In Arapahoe County Colorado. While there, I observed PR well During this inspection the following possible compliance issues were observed: Weeds unmanaged on location. Rule 606. 8/24/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	07/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506080	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641969