

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

693807517**FIELD INSPECTION FORM**Loc ID 334373 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Roberts, Jake		jroberts@americanhelium.us	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284177	WELL	PR	11/01/2023	GW	113-06214	HC STATE 36-43B-45-15	PR
284572	WELL	PR	11/01/2023	GW	113-06215	HC FED 1-13-44-15	PR

General Comment:

ECMC staff performed a routine field inspection on 7/23/2024.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/24/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 435-631-2239

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe barricade		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		38.103537,-108.470063
Comment:	Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 08/30/2024

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284177	Type:	WELL	API Number:	113-06214	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing - plunger lift								
Corrective Action:	Wells shall be shut in immediately. By Order 1v-937 Paradox Upstream LLC right to conduct oil and gas operations in Colorado has been revoked. Paradox is no longer authorized to sell or transport produced hydrocarbons from any of its wells. The well must be shut-in until an approved operator has obtained the appropriate authorization to operate this well. Specifically, the well must be transferred to an approved on an approved Form 9. In addition, The approved operator must submit a Form 3, Financial Assurance Plan, and a Form 10, Certificate of Clearance.						Date:	07/29/2024	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284572	Type:	WELL	API Number:	113-06215	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing - plunger lift								
Corrective Action:	Wells shall be shut in immediately. By Order 1v-937 Paradox Upstream LLC right to conduct oil and gas operations in Colorado has been revoked. Paradox is no longer authorized to sell or transport produced hydrocarbons from any of its wells. The well must be shut-in until an approved operator has obtained the appropriate authorization to operate this well. Specifically, the well must be transferred to an approved on an approved Form 9. In addition, The approved operator must submit a Form 3, Financial Assurance Plan, and a Form 10, Certificate of Clearance.						Date:	07/29/2024	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807518	Inspection photos 7/23/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642321