

**Inspection Photos**  
**Location Name: BM Federal #13-12**  
**API: 05-081-07395**



**The 1" valve was leaking during this inspection.**

**A new 2" valve and plug have been installed since the last field inspection of this location.**

**Inspection Photos**  
**Location Name: BM Federal #13-12**  
**API: 05-081-07395**



**BLM tag remains on 2" valve upstream of recently installed 2" valve and plug.**

**During this inspection, ECMC staff installed a 1" valve to stop leak.**