

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2024

Submitted Date:

07/31/2024

Document Number:

713900807**FIELD INSPECTION FORM**Loc ID 305609 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 03801**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		joeforma@obenergy.com	
Burns, Adam		adam.m.burns@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279948	WELL	SI	07/01/2020	GW	123-23239	LOST CREEK 27	RI
305609	LOCATION	AC			-	LOST CREEK-63N62W 16NESW	RI

General Comment:[This is an Interim Reclamation and Stormwater Inspection.](#)

Location

Lease Road:			
Type			
comment:	Overgrown vegetation along the access road has not been managed per comment in FIR #699107568. Overgrown vegetation can pose a fire hazard as well as having the potential to spread in the case of undesirable weedy species.		
Corrective Action:	Comply with Rule 1002.e to maintain access roads.	Date:	08/07/2024

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type			
Comment:	Vegetation along the well pad remains overgrown despite the previous FIR #699107568. Refer to inspection photos for details.		
Corrective Action:	Operator should comply with Rule 606 to remove vegetation on the well location. The corrective action date shall remain 10/25/2023 since it has not yet been resolved.	Date:	
Type			
Comment:	Debris along the well pad remains overgrown despite the previous FIR #699107568. Refer to inspection photos for details.		
Corrective Action:	Operator should comply with Rule 606 to remove debris on the well location. The corrective action date shall remain 10/25/2023 since it has not yet been resolved.	Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	279948	Type:	WELL	API Number:	123-23239	Status:	SI	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	305609	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas has not met Rule 1003 standards and will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Inspector Name: Hansen, Logan

Comment:						Date _____
Corrective Action:						
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
<u>Storm Water:</u>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div style="display: flex; justify-content: space-between;"><div style="width: 15%;">Comment:</div><div style="width: 70%; border: 1px solid black; padding: 5px;"><p style="color: blue;">At the time of this inspection, no erosion issues were observed at the location or along the access road.</p><p style="color: blue;">Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.</p></div><div style="width: 15%;">Date: _____</div></div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"><div style="width: 15%;">Corrective Action:</div><div style="width: 70%; border: 1px solid black; height: 20px;"></div><div style="width: 15%;">Date: _____</div></div>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900808	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646924