

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2024

Submitted Date:

07/25/2024

Document Number:

694100401

## FIELD INSPECTION FORM

Loc ID 424387 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS
,		Inspections@civiresources.com	All Inspections
Carveth, Cole		cole.carveth@crestonepr.com	

**General Comment:**

This is an environmental inspection for Location ID 424387 Liberty 2-21 battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:		Open excavation on site from recent spill. Impacted soils have been remeoved. Awaiting confirmation sample results. Form 19 has been submitted.			
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type					
Comment:	Orange construction fencing around the open excavation is falling down, needs to be re-secured.				
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C				Date: 08/08/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Open excavation due to recent spill. Surrounded by orange fencing. Awaiting confirmation soil samples. .

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403866473	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639553">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639553</a>
694100402	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639547">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639547</a>