


**Operator: HPR**

**Location Name: Garden Creek 06-11H**

**Loc ID: 415772**

**Inspection: 693700441**



☉ 101°E (T) ● 40.931259, -104.279983 ±25ft ▲ 5112ft



Garden Creek 6-11H  
24 Jul 2024, 2:19:24 PM

SE 120 150 S 180 SW 210 240 W 270

199°S (T) • 40.931259, -104.279983 ±18ft ▲ 5112ft



Garden Creek 6-11H  
24 Jul 2024, 2:17:05 PM

S 180 SW 210 W 270 NW 300


238°SW (T) • 40.931259, -104.279983 ±25ft ▲ 5112ft



Garden Creek 6-11H  
24 Jul 2024, 2:16:48 PM



Garden Creek 6-11H  
24 Jul 2024, 2:14:48 PM



**CA:** Small spill localized beneath ECD. Cleanup spill and identify cause of release ECD and repair.

**CA Resolution:** Operator has provided follow-up to show that noted spill has been appropriately addressed to comply with the 900 series.

**CA:** COGCC Environmental Inspection of Spill ID 470406 separator over pressure and PRV release. Oil spray remains on separator and ancillary electrical equipment. Road base has been removed near separator and around pipe/electrical chase and pad for control box. No soil stockpiled on location. No confirmation soil sample results received. Submit confirmation soil samples with analysis for TPH (C6-36) and BTEX from spill area on a Form 19 Supplemental Report along with root cause of separator overpressure.

**CA Resolution:** Operator has provided follow-up to show that noted spill was appropriately addressed and Form 19 Doc #: 402275143 was submitted.