

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2024

Submitted Date:

07/29/2024

Document Number:

711901006

FIELD INSPECTION FORM

Loc ID 316953 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		gfritzler@bresnan.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233447	WELL	SI	03/01/2024	OW	121-05489	WITTENBERG 4	SI

General Comment:

ROUTINE FIR

Location

Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROADS		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	REMOVE OR INSTALL BELT SHROUD LAYING ON GROUND		
Corrective Action:	COMPLY WITH RULE 606	Date:	08/05/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment: NONE

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 233447 Type: WELL API Number: 121-05489 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: REMOVE OR INSTALL BELT SHROUD AT PJ

Corrective Action: COMPLY WITH RULE 606 Date: 08/05/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403868992	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642797
711901057	PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642782