

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403833079

Date Received:  
06/24/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 696306459

Inspection Date: 06/20/2024

FIR Submit Date: 06/20/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 424418

Location Name: Antelope Number: 11-20 County: \_\_\_\_\_

Qtrqr: NWN Sec: 20 Twp: 5N Range: 62W Meridian: 6  
W

Latitude: 40.390690 Longitude: -104.354070

### FACILITY - API Number: 05-123- -00 Facility ID: 424418

Facility Name: Antelope Number: 11-20

Qtrqr: NWN Sec: 20 Twp: 5N Range: 62W Meridian: 6  
W

Latitude: 40.390690 Longitude: -104.354070

### CORRECTIVE ACTIONS:

1 ☒ CA# 196016

Corrective Action: Comply with Rule 606

Date: 07/19/2024

Response: CA COMPLETED

Date of Completion: 06/24/2024

Operator  
Comment:

Operator has reported that the identified fallen panels have been appropriately fixed/re-installed to comply with Rule 606.

ECMC Decision: Approved

ECMC  
Representative: Approved

2 ☒ CA# 196017

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b

Date: 07/19/2024

Response: CA COMPLETED

Date of Completion: 06/24/2024

Operator  
Comment: Operator has reported that all identified risers have now been appropriately marked to comply with Rule 1105.b.

ECMC Decision: Approved

ECMC  
Representative: Approved

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 6/24/2024 9:26:41 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403833079	FIR RESOLUTION SUBMITTED
403833081	Inspection Report Resolution

Total Attach: 2 Files