

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403841592

Date Received:  
07/01/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306475  
Inspection Date: 06/26/2024 FIR Submit Date: 06/26/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 420880

Location Name: Antelope Number: I-17 County: \_\_\_\_\_  
Qtrqr: NESW Sec: 17 Twp: 5N Range: 62W Meridian: 6  
Latitude: 40.395910 Longitude: -104.351800

FACILITY - API Number: 05-123-00 Facility ID: 420880

Facility Name: Antelope Number: I-17  
Qtrqr: NESW Sec: 17 Twp: 5N Range: 62W Meridian: 6  
Latitude: 40.395910 Longitude: -104.351800

CORRECTIVE ACTIONS:

1  CA# 196179

Corrective Action: Comply with Rule 606 Date: 07/12/2024

Response: CA COMPLETED Date of Completion: 06/28/2024

Operator Comment: Operator has reported that identified debris/tumbleweeds have been addressed/cleared from the location to comply with Rule 606.

ECMC Decision: Approved

Approved

ECMC  
Representative:

2  CA# 196180

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

Date: 07/12/2024

Response: CA COMPLETED

Date of Completion: 06/28/2024

Operator  
Comment:

Operator has reported that identified risers have been appropriately marked to comply with Rule 1105.b.

ECMC Decision: Approved

ECMC  
Representative:

Approved

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 7/1/2024 11:43:03 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403841592	FIR RESOLUTION SUBMITTED
403841596	Inspection Report Resolution

Total Attach: 2 Files