

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2024

Submitted Date:

08/02/2024

Document Number:

694500705**FIELD INSPECTION FORM**Loc ID 312756 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10386Name of Operator: POC-I LLCAddress: P.O. BOX 51208City: CASPER State: WY Zip: 82605**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chamard, Megan		megan.chamard@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Podio, Rebecca	307-746-6468	rpodio@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480890	TANK BATTERY	AC	10/07/2021		-	Iles Dome Tank Battery	EI
486930	SPILL OR RELEASE	AC			-	Ilse Dome Tank Battery	EI

**General Comment:**

On 7/24/2024, ECMC staff; Kris Neidel and Alex Fischer inspected the Iles Tank Battery and spill 486930 and Remediation project 34712. The following was observed: in the area of spill, hydrocarbon staining was observed just below the surface. fluid was observed in the cement sump structure. Corrective Actions: Per Rule 913.e, quarterly reporting on a form 27 shall be submitted. Spill 486930 shall be delineated for Table 915-1. Any corrective action(s) from previous inspections that have not been addressed are still applicable. See attached From Form 27 Doc # 403723111:COA: "Operator anticipates the remaining cost for this project to be: \$200,000. Within 30-days of Staff approval of F27 Doc #403723111, Operator to provide a detailed task and cost breakdown for the \$200,000." Corrective Actions; Submit a report of work completed on a Supplemental Form 27 (Remediation Number 28244), the last update was March 19, 2024(doc # 403723111). See attached Photos.



Environmental

Spill/Remediation:

Comment:

in the area of spill 486930, hydrocarbon staining was observed just below the surface

Corrective Action:

Spill 486930 shall be delineated for Table 915-1 with results submitted via Form 19.

Date:

09/06/2024

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403875660	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650107">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650107</a>
694500706	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650103">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650103</a>